

# IMPORTANT NOTICE c60603-1023

## Standardized Volume

Software and Firmware version c60603-1023 contains a new setting for the temperature used to calculate Standardized Volume. This was added to support international customers that use a different temperature than the US EPA. The US EPA temperature is 20°C

Once the upgrade has been performed it is necessary to check the temperature value. This can be found on the Config/Utils screen accessed via the main screen once connected to the console.

The screenshot displays the 'Config/Utilities' interface for the XC6000 device. The title bar reads 'XC6000: Config/Utilities: - 192.168.10.61 Apex Rental / Demo TSG'. The interface is divided into several sections:

- Left Panel:** Contains buttons for 'Stats', 'Set Clock' (highlighted with a blue border), 'Console Audit', 'Comm. Check', 'Reset Console', 'Clear Current Run', and 'Check Data File'. Below these are checkboxes for 'Enable Profile Name Auto Numbering' and 'No Background Pictures', and a 'Trap Probe Heaters' section with two vertical bars.
- Center Panel:** Features a 'Connection Method' section with radio buttons for 'TCP/IP' (selected) and 'USB / COM Port'. Below this is a table for 'IP Address' (192.168.10.61) and 'Port #' (81), with a red label 'USB / COM Ports' underneath. At the bottom, a yellow box states 'Currently Connected Using IP# 192.168.10.61:81'.
- Right Panel:** Includes 'Units and Formats' with radio buttons for 'Metric' and 'Hybrid' (selected), and checkboxes for '24Hr Clock' and 'dd-mm-yy'. Below is a 'Protected password' field, 'Monitor Screen', and 'Calibrations' buttons.
- Bottom Panel:** Contains a 'Firmware Update' button, a 'Help' button, and a 'Close' button. The status 'SD' is visible in the bottom right corner.

The 'Standard Temperature' field is circled in red, showing a value of 20 °C. Below it are checkboxes for 'Enable Automated Testing' (checked) and 'Allow Modbus to Start Test' (unchecked). The 'Modbus Wait' field is set to 60 (1-250 Sec.) for the DAS to get FINAL test data. The 'Versions' section at the bottom left shows: Software: C60603, Firmware: 1023, DSP: ?, and Modbus: ?.

Contact the Apex Technical Services Group at [support@apexinst.com](mailto:support@apexinst.com) or 919-557-7300 with any questions